DEPARTMENT OF TOXIC SUBSTANCES CONTROL (REGION 3)

1405 N. SAN FERNANDO BOULEVARD, SUITE 300 BURBANK, CA 91504 (818) 567-3000



SURVEILLANCE AND COMPLIANCE REPORT HAZARDOUS WASTE GENERATORS/ TRANSPORTERS/TSDFs

Cin -426 224	Date of the	spection 10 126 22/92
CAD008383291	Inspector's Na	ame:
EPA I.D. #	Mailing Address:	Ownership:
Facility Name/Address:	+ P.O. Box 2108	
Power. Ne Oil Co	•	
santa Fe Springs		
CA, 5067		Barrage many many
County Los Anjeles	Type of business:	Persons present:
	O. I REFINERY	DISC: Robert Kon
Contact Person		Pomorie: Ted& Me
Teld Metro Se		The chis
Phone # <u>(213) 99 4 - 6/11</u>		Judi GHA
Samples taken?	[Yes (receipt attached)	[] Nc
Plan of Correction necessary?	[+Yes (Due date: 11/6/92	
Discussions with Management:	Consent For supply, philips	youghs, valkolough, Rocard
Discussions with Management: Sowhold by June Chr 1) Records - - 2) WAIK +hro Facility operating under: [/]	Consent For sayling, philosophics of some will be several additional document by Tel Metrose The See back SD(A/Ky) [] Permit	reviewed will be si
Discussions with Management: Scaled by June Chr I) Records — T) WA/h + how Facility operating under: [/]! On this date an inspection of you Health and Safety Code (H&SC) collection of samples or other evice of Section 66272.1, Title 22, California Contine H&SC: Title 22, California Contine Contin	Consent for smyling, philipsishmon. Supplied Record will be several add haml docume by Ted Metrose SD(A/Ky) [] Permit Ur facility was conducted under autand Section 66272.1, Title 22, Caldence, including the taking of photographic Code of Regulations; or Code of Fedothe generation, storage, handling,	[] Other
Discussions with Management: SCARD 69 JUNC Chr I) Records — T) WA/h + hro Facility operating under: [/]! On this date an inspection of you Health and Safety Code (H&SC) collection of samples or other evic of Section 66272.1, Title 22, California C above. These violations relate to hazardous and extremely hazardo. Authorized Representative of Firm	Consent for smyling, philipsishmon. Supplied Record will be several additional document by Ted Metrose SD(A/Ky) [] Permit In facility was conducted under authorized of Regulations. Specific ode of Regulations; or Code of Fed the generation, storage, handling, us waste.	[] Other
Discussions with Management: Scaled by June Chr I) Records— The Chr The Chr I) Records— The Chr	Consent for simpling, philips of solutions. Supplied Record will be several additional document by Ted Metrose Supplied Record will be several additional document by Ted Metrose Supplied Record will be several additional document by Ted Metrose Supplied Record will be several additional document by the section 66272.1, Title 22, Caldence, including the taking of photographic productions of Regulations. Specific ode of Regulations; or Code of Fed the generation, storage, handling, us waste. Authorized Supplied Record will be several additional document by the section of the generation, storage, handling, us waste. Name 6	[] Other
Discussions with Management: Scaled by June Chr I) Records— The Chr The Chr I) Records— The Chr	Consent for smyling, philipsishmon. Supplied Record will be several additional document by Ted Metrose SD(A/Ky) [] Permit In facility was conducted under authorized of Regulations. Specific ode of Regulations; or Code of Fed the generation, storage, handling, us waste.	[] Other
Discussions with Management: Scaled by June Chr I) Records— The Chr The Chr I) Records— The Chr	Consent for simpling, philips of solutions. Supplied Record will be several additional document by Ted Metrose Supplied Record will be several additional document by Ted Metrose Supplied Record will be several additional document by Ted Metrose Supplied Record will be several additional document by the section 66272.1, Title 22, Caldence, including the taking of photographic productions of Regulations. Specific ode of Regulations; or Code of Fed the generation, storage, handling, us waste. Authorized Supplied Record will be several additional document by the section of the generation, storage, handling, us waste. Name 6	[] Other

\$ 2) welk through - Storinge Area

- A) NO H.w. SIN
- B) Several draws open/imposely closed
- C) Several drums with No physical (Numerous) properties/state.
- D) Numerous drums with no cheater thanks
 Character 15 tres.
- E) Numerous drums with No Accumulation Stort date F) ONE Leaking Drum
- 3) Drums in Storge area need not be be attained as European Pursuant to Section 7,74 22 66272.1 rs
 requested on 10/16/92

HAZARDOUS MATERIALS	1. Authorization Number	HML No. 920604 2. Page
SAMPLE ANALYSIS REQUEST	HMIIAZII	TO 9720614 1 of 2
3. Requestor: Meno Herry Hez Address (To Receive Results): 140511. Sunf	4. Phone (818) 567-3024 Enversion 1814, Phone 91:64-	5. Priority 💪 a. Authorized by
6. Date Sampled 10-22-92	7. Time Sampled • Hours	8. Codes (fill in all applicable codes)
9. Activity: ⊈SEB □ SMB □ FPB	□ATD □PASD □Other	a.STC 3050 b.Region 3
10. SAMPLING LOCATION	0083832 91 1,	c. TPC
b. Site Powerine Oil C	a, EPA ID No.	d. INDEX 6300 e. PCA 32005
0.316		e. PCA 32005
c. Address 12354 Lakela	nd Santate 90670	g. County 3
11. SAMPLES		기가 되는 것이다. 그렇게 하다고 되었다. 그렇게 모르는 이 라고를 잃었다고 하셨다.
a. ID b. Collector's No. c. Lab No.	Sample Container d. Type e. Type f. S	Size g. Field Information
A PR-mH-01 9200		certalyst
B 02 9206 c 03 9206		Zinc-oxide (atalys
0 04 9706		catalyst
E 05 9204		
F 06 9200 G 07 9200	A CONTRACT OF THE PARTY OF THE	dessicut beens
H V J 08 9206		chorcoal
12. ANALYSIS REQUESTED f.	PCB	k. ☐ Ext. Org
a. □ pH g.	□ voa-h/s	(Screening) i. □ Flash
시자기 교육 회속 공개 시 . ^ . ^		Point
[™] Scan	□ VOA-8240	
	□ VOA-8260	n. 🗖
(Spec) d. □ W.E.T j.	□ SVO-8270	o. 🗆
13. SUPPLEMENTAL		Initials
REQUESTS		Date
14. CHAIN OF CUSTODY a. SCE OCICILIDOL	0000 000	tody / / /
Signature	Nanhe/Title	A I 22 Inclusive Dates
b. Ulland Trans	Levana Hannon	Inclusive Dates
C. Signature	Name/Title	Inclusive Dates
d:		
Signature 15. SPECIAL REMARKS:	Name/Title	Inclusivo Dates
16. ASSIGNED TO:		Date
17. LAB REMARKS:		

HAZARDOUS MATERIALS	1. Authorization Number	HML No.920604	2. Page
SAMPLE ANALYSIS REQUEST	HMINALLE	To 920614	
Requestor Memory Henry XICZ Address (To Receive Results) 140511. XIII Fer	4. Phone (187) 6 1 - 024 1 curlo Islad, Burrik 91764-	5. Priority 4. a. Authorized by	
6. Date Sampled 10-22-97	7. Time Sampled • Hours	8. Codes (fill in all applicable	e codes)
9. Activity: √□ SEB □ SMB □ FPB	□ ATD □ PASD □ Other	a.STC ▷ ▷ Ş ▷ b.Region ß	
10. SAMPLING LOCATION	008382291	c. TPC	
	a. EPA ID No.	d. INDEX 6 3 0 0	
b. Site Howerine Onl	プラン・グラン・コンス かんかん あんしょ 大道道 しょうしゃ マンデリケー カン・ディング さんけんけん	e. PCA	5
c. Address 12354 Lake Virx	1 Senta Fe 90670	f, SITE g. County 3 7	
Number Street 11. SAMPLES			
a. ID b. Collector's No. c. Lab N	Sample Container o. d. Type e. Type f. S	Size g. Field Informa	tion
A PL-174-09 92061	12 50110 class	<u>Sarl pain</u>	
$\frac{B}{c} + \frac{10}{11} = \frac{92.06}{9200}$		<u> </u>	M. GARILLO
D			
G			
12. ANALYSIS REQUESTED f.	□ PCB	k. ☐ Ext. Org (Screening)	
a. □ pH g.	□ VOA-H/S	∴ i. □ Flash Point	
T .	□ VOA-8240	_ m. 🗇	
Wierais	□ VOA-8260	n. 🗆	
(Spec) d. □ W.E.T j.	□ SVO-8270	_ o.□	
13. SUPPLEMENTAL		Initials	
REQUESTS		Date	
14. CHAIN OF CUSTODY	chain of custod	V / / -	1 1
6 Dicha Signature Lauren	Tercina Hannon/	(A 11 02 97 -	Dates /
Signature	Name/Title	Inclusive	
Signature	Name/Title	Inclusive	
d. Signature 15. SPECIAL REMARKS:	Name/Title	Inclusive	Dates
16. ASSIGNED TO:		Date	
17. LAB REMARKS:			

Hazardous Materials Laboratory 2151 Berkeley Way Berkeley, CA 94704 (415) 540-3003

Sample Receipt

Authorization	No. Hm I 1421		
HML Sample No	(s) 9 <u>70604-920614</u> c	ollector's N	10(s). <u>PR-MH-01 thrull</u>
Custody Seals	Present	Absent	Broken
If p	present, location on	sample(s)	
Sample Sondit	Acceptable Sample container re Samples received in Insufficient sample Sample Analysis Req sample(s) Discrepancies betwe Form(ARF) and the S Discrepancies betwe samples Sample Analysis Req	improper convolume/weignest form no ample Analysen SAR information of numbered toomplete thout proper	ontainer ont for analysis of received with the orization Request sis Request(SAR) mation and the or illegibly labeled r preservation
Action taken	None Sample analyses on Inform sample colle Samples analyzed as Other(specify)	ctor of prob received	olem .
Name (Print) Teranala	Initial	Date 5	State if Corrected
Supervisor's	approval		

HML#920604-920614 led from Region 3





AIRBILL PACKAGE TRACKING NUMBER

5069075373

22114 5067	בובוט					
	Date 10-29-92			RECIPIE	NT'S COI	PY
From (Your Name) Please Print		mber (Very Important)	To (Recipient's N	lame) Please Print	R	ecipient's Phone Number (Very Impo
RUSS CHIN		20-3376 partment/Floor No.	PAM SC	HIROZSAMPLE R	RECEIVING(510) 540-3101 Department/Floor
SOUTHERN CAL LA		paramento roca rvo.	DEP	F. OF HEALTH ZARDOUS MATER TESS (We Cannot Deliver to P.O. 8	SERVICES RIALS_LABS	
Street Address	1	3		ress (We Cannot Deliver to P.O. B PEINZ, STE 15		
City	State ZIP Require	ed ,	City	The second secon	State	ZIP Required
LUS ANGELES	CA 90	026	Berk	eley,	CA ?	94710
YOUR INTERNAL BILLING REFERENCE INFORMATION	OM (optional) (First 24 characters will appear on in	nvaice.)	D	IF HOLD FOR PICK-UP, Print I Street Address	FEDEX Address Here	
PAYMENT 1 Bill Sender 2 Bill Recipient's Fo	SEE SEE SEE SEE SEE	4 Bill Credit C		City	State	ZIP Required
SERVICES (Check only one box) 5	DELIVERY AND CRECIAL MANDLING	PACKAGES WEIGHT in Pounds Only	YOUR DECLARED VALUE	Emp. No.	Date	Federal Express U
Priority Overnight (Delay by next business manage) (Delay by next business atternoom. (So Salviday (severy))	1 HOLD FOR PICK _T UP (Fill in Box H) 2 PLOELIVER WEEKDAY	1 21/4	54100(1)		hg. To Del.	Base Charges To Hold Declared Value Char
18 FEDEX LETTER 56 FEDEX LETTER	3 DELIVER SATURDAY (Extra charge)			Street Address		Other 1
12 FEDEX PAK* 52 FEDEX PAK*	4 DANGEROUS GOODS (Extra change)		1	City	State 2	Zip T
13 PEDEX BOX 53 PEDEX BOX	I₃⊟	Total Total	Total		-	Other 2
14 PEDEX TUBE 54 FEDEX TUBE	6 DRY ICE Lbs.	21/35		Received By:	5- Gil	Total Charges
Economy Two-Day gainer by second number of the control of the cont	7 OTHER SPECIAL SERVICE	DIM SHIPMENT (Cha	rgeable Weight)	7 70000	FedEx Employee Nu	PART #137204 FXEM
41 GOVT PACKAGE Freight Service (for packages over 150 fb.)	9 SATURDAY PICK-UP (Estra charge)	L_x_V	<u>/ </u>			12L
70 OVERWIGHT 80 7NO-OAY FREIGHT**		Receive 1 ☐ Regular Stop	3 ☐ Drop Box			© 1981-92 REDEX
Delivery commitment may Delivery commitment may Delivery commitment may Delivery commitment may	12 HOLIDAY DELIVERY (Il offered) (Estra charge)	2 Ti On-Call Stop	4 □ B.S.C. ■ 5 □ Station	Release Signature:		UBA

HAZARD APPRAISAL AND RECOGNITION PLAN PRESITE VISIT FORM

HAZAKU APPRAISAL AND RECOGNI	•
Prepared By: (2) Helms Mens" Helmander	SECTION E. BASIC INFORMATION ON POTENTIAL HAZARDS
, J J	(Attach copies of HARP Chemical Data Sheets or other appropriate information as suggested in instructions.)
Date: 10/21/47	
Phone: (\$18) 567-3021	SECTION F. EXPOSURE CONTROL METHODS
Responsibility Name Unit/Agency Lead Field Staff	☐ Engineering
Many Hermalez FMA Leadenson	Describe: Avail unknow wiste stores week
1 Robert town the Land Note that	people PPE accidently reporteding
& tothlew Yotata 755B Indistrict Hyon	Avel de prid - I.Ne of Exposure
4 TIMA GOLICIEZ INB I Soupley	Brock inth two teams, have two
5. Lang Stock TMB 1 Seaper	NIN Stall Prisons (#396) 10 through
6. Yesser Areke TAB 2" Septer	SECTION G. REQUIRED PERSONAL PROTECTIVE EQUIPMENT
SECTION B. SITE DESCRIPTION	Level of Protection: $\square B \boxtimes C = \square D (w_0 / k / k/3 w_0 k)$
Site Name: Paringe 0:1 ()	Glove(s): Outer = O, Inner = 1 Suit:
PCA No.: Project # WP	Cotton/Vinyl Cloth Coveralls
Address: 123511 Likelead Rd	Silver Shield/4H
City: Sen To FC Spirit State: CA Zip: 90670	Neoprene P. E. Tyvek Som Mer IN
Site Phone No.: (2/3) 9 1/4-9861	O Nitrile Saranex Level C with
NOTE: Attach Map of Site and Directions to Hospital	PVC/Monkey Glip □ PVC F.E. 'Yve K Grip Glove/Kevlar □ Baracade/Chemtuff
Contact Person: Teld Mc 41052	Viton Other; Other;
Type of Operation/Waste Stream (Describe):	Respirator: A/P Cartridge: 6 M C - 1-
Civile oil pakes voices grades or	SCBA Escape (ELSA — 5 Min.)
	Other Safety Gear:
Purpose of Visit (Describe): Selwal V.3/1 Tollow	☐ Binoculars
This visit is for Drum Surphy	☐ Boot Covers ☐ Safety Vest
Site Visit Date(s): 15-27-92	☑ Boots ☐ Two-Way Communication Kit
Estimated Time on Site: Hours/Day Days	⊠ Eye Protection ☐ Other:
Nearest Hospital and Address: White fees byteries	Hard Hats
15-15/ E JiNINE OF	SECTION H. SURVEY EQUIPMENT
Phone No.: (273) 945-3561	Computible Gas/Ovygen Meter
SECTION C. NUMBER OF SAMPLES TO BE COLLECTED	Photoionization Detector Probe: 11, 7 9 10, 2
Air Surface Impoundment	Organic Vapor Analyzer (OVA) TLV Sniffer
Drums(s) 16 + Sell + Surface Water	Drager Tubes (Specify:)
Groundwater Tank(s)	☐ pH Meter/Paper ☐ WBGT Meter ☐ Noise Dosimier
Soil/Sediment Waste/Sludge	Safety Vest Proposed work
Sump/Pit Other	Two-Way Communication Kit rest
SECTION D. POTENTIAL HAZARDS	☐ Binoculars ☐ Radiation Meter (Victoreen 400)
Chemical Hazards 2. Physical Hazards	Aerosol/Particle Monitor (VOther (Specify: 1/2 a 1/4/ a 1
Carcinogens Confined Space	
Corrosives H. F. (Source:)	SECTION I. OTHER HYGIENE AND SAFETY EQUIPMENT
☐ Developmental Health ☐ Heat or Cold Stress (Expected	Available On Site Bring
Hazards (Teratogen)° F)	Canopy/Tarp/Umbrella
Dusts Machinery/Construction	Drinking Water
Explosives Noise (Source/Decibels):	Shower/Eye Wash
☐ Flammables ☐ Oxygen Deficiency ☐	Fire Extinguisher
Inorganic Vapors Gases Radioactive Materials Metals	First Ard Kit
Oxidizers 3. Biohazards	Plastic Sheeting/Buckets/Bags
□ PCBs 4. ☑ Other (Specify):	Portable Toilets
Pesticides Cotte Cotte Fines.	☐ ॄ् Washing Facilities
	VESECTION J. PERSONAL MONITORING
Skin Absorption Sin Skin Absorption	Heart Rate Oral Temperature
Solvents Foot Meterits State of Descent	Do You Need Industrial Hygiene Monitoring? Yes No
(Use this space to describe hazards)	If Yes, What Type? Noise Air Other (Specify: PLACE YELL)
South wild be drawn from	SECTION K. REVIEW/APPROVAL
Known wester Streems. Facility oformer	Win Clath Lilan
- Small stage and open gill closes,	10/21/9/
South terns Shell be Split IN	Health and Safety Unit (Review) Dyfic
two's for effectively.	Ky Yeann 16-121-92
	Superviside Approval) Date
	trait,
·	

OCT 19 RECT

POWERINE OIL COMPANY

12354 LAKELAND ROAD SANTA FE SPRINGS, CA 90670

TELEPHONE: (310) 944-6111 TELECOPY NO: (310) 944-8522

DATE: 10/19/92 TIME:	-
COMPANY: Dept. of Touc Substance Control	
FAX NO.: 818/547-3129	_
FROM: June Christman	
SUBJECT	_
MESSAGE:	-
	_
· n-	Ė
	_
	_



POWERINE Oil Company

12354 Lakeland Road, P.O. Box 2108 Santa Fe Springs, California 90670-3857 (310) 944-9861 (310) 944-6111



TLX No: 4720404 A/B Powerne Telecopy No: 944-8522

VIA FACSIMILE

October 19, 1992

Guillermo A. Hernandez California Environmental Protection Agency Department of Toxic Substances Control (DTSC) Region 3/Facility Management Branch 1405 N. San Fernando Blvd., Suite 300 Burbank, California 91504

Subject: Review of DTSC Requests Made During Facility Inspection

on October 16, 1992

Dear Mr. Hernandez:

Per your facility inspection of October 16, 1992, we understand you need copies or other supporting verification of the following:

- The Interim Status Document (ISD) Waste Analysis Plan, Closure Plan, and Closure Cost Estimate pertaining to the Alkylation Neutralization Unit (ANU);
- 2) Evidence of an agreement by a local hospital to handle Powerine emergencies including planned response to a hazardous waste emergency, particularly from the ANU;
- 3) A list of tank/container inspections excluded recyclable materials and hazardous waste, especially in the ANU;
- 4) List of emergency equipment used to respond to the release of hazardous waste and other related emergencies;
- 5) Training records for Judi Gardner and Emergency Response personnel, Bill Ingraham, John Magaña, and Craig Neighbarger. Note: a previous request for documentation of ANU operators training was rescinded;
- 6) Laboratory analysis of wastes and recyclable materials from our profile/characterization notebook marked by Ms. Kathleen Yokota;
- 7) Verification, either directly with or via USA trucking that the ultimate receiver of excluded recyclable materials, principally from California Portland Cement Company is in fact

POWERINE Oil Company

California Environmental Protection Agency Department of Toxic Substances Control (DTSC) October 19, 1992 Page 2

receiving the material and managing the material properly.

- 8) Waste profile breakdowns from the Laidlaw in Buttonwillow for the "waste filter" stream;
- 9) Acceptance letter from the Chemical Waste Management facility for the "facility clean up" stream;
- 10) Records of the County Department of Health Services oversight of the recent naphtha line leak on Lakeland Road;

We are now in the process of copying the regulated documentation and securing additional verification. Please contact me should you require any additional information prior to your inspection during the week of October 19, 1992.

Sincerely,

June M. Christman

Manager - Environmental

Engineering

MAW/DTSC1016.doc

cc: M. Gnagy

G. Gardner

J. Magaña

T. Metrose

M. Winefield

File

DEPARTMENT OF TOXIC SUBSTANCES CONTROL

1405 N. SAN FERNANDO BLVD., SUITE 300 BURBANK, CA 91504

Oct 22 92



Powarne Oil Co 12354 Lacreand Rd 90670 Santa Fe Springs CA 906'1 Sprit Sample RECEIPT

Received from representatives of the Department of Toxic Substances Control on a requested sample split from samples acquired under the authority of Section 66272.1, Title 22, California Code of Regulations. oblucated

The samples are numbered as follows:

Signatures:


Area 8-L: Nazardous Waste Accumulation Area

EXCLUDED RECYCLABLE MATERIALS	Recycle Facility	Character- ization if not <u>Recycled</u>	<u>Basis</u>
1 Activated Alumina Catalyst 2 FCC Equillbrium Catalyst 3 AKZO KF842 Unifiner Catalyst 4 FHT R-1 S424 Catalyst 5 H2 HY-V-6" Catalyst	Kiln Kiln Kiln Kiln Kiln	Non-Haz Non-Haz See 12 CA-Haz CA-Haz	MSDS TTLC TTLC MSDS - due to Cu
6 ZINC OXIDE Catalyst 7 UCI -20 CO-moly Catalyst 8 Coke Fines 9 Dessicant 10 Jet Clay 11 Charcoal 12 Unifiner Cat - HR1 13 Sand blast media	Kiln Kiln Coker Kiln Kiln Coker Kiln Kiln	CA-Haz CA-Haz Non-haz Non-haz RCRA-Haz RCRA-Haz CA-Haz	MSDS - due to Zinc TTLC MSDS STLC FP FP,TCLP,TTLC,STLC,Bio TTLC TTLC TTLC
14 Spent used oil 15 Dimethyl disulfide 16 Ethylene glycol	Slop oil Lomax Refinery	CA-Haz RCRA-Haz	Listed MSDS Listed
HAZARDOUS WASTE 16 Chrome Balls 17 TGU Solid Wst 18 Nonreuseable catalyst 19 Ethylene Dichloride 23 Propylene oxide	TSDF Facility Chem Wst Chem Wst Chem Wst	CA-Haz	Basis TTLC TTLC TTLC Listed Listed
NON MAZARDOUS MASTES 20 Filters 21 Facility Clean up 22 Nonreuseable FCC Fines	<u>Facility</u>	Char Non-Haz Non-Haz Non-Haz	Basis FP,TCLP,Reac,STLC,PCB TCLP,TTLS, STLC TTLC

Area 8-N: Gasoline Bulk Terminal Storage Tarks

Hazardous Material

1 Gasoline



POWERINE OIL COMPANY

MATERIAL SAFETY DATA SHEETS

LOCATION INFORMATION

Material Safety Data Sheets (MSDS) on all chemicals found in our refinery have been compiled into a six volume set of manuals. Each individual MSDS has been assigned (by chemical name) a P.O.C. number and arranged in alphabetical order in the MSDS Manuals.

NOTE: REFER TO THE MSDS INDEX INSTRUCTIONS TO ASSIST IN THE USE OF THE MANUALS

These manuals are intended as a reference source and are available to all employees 24-hours a day. Also included in the MSDS Manual is a copy of our compliance program, instructions on how to interpret an MSDS and a copy of California's Code of Regulations General Industry Safety Orders (G.I.S.O.), Section 5194. The MSDS Reference Manuals are green in color and are located as follows:

- 1. Safety Department
- 2. Warehouse #1
- Gate 4
- 4. Photocopy Room East Lab entrance door
- 5. Environmental Department
- 6. Tech Services Department
- 7. Heavy Oil Control Room (Division C)
- 8. Long Beach Marine Terminal Bridge set

HAZARD COMMUNICATION COORDINATOR: Craig Neighbarger, Ext. 467

FOR EMERGENCY MEDICAL ATTENTION: Call 77 (Fire Department)

NON-EMERGENCY MEDICAL ATTENTION: WorkCare (310) 698-0811 (Whittier Presbyterian Hospital)

POWERINE OIL COMPANY

PROPOSITION 65

Proposition 65 requires that a clear and reasonable warning be given to persons exposed to listed chemicals. The governor publishes a list of chemicals "known to the state to cause cancer or reproductive toxicity." This POC facility refines, transports and stores crude oil, petroleum and chemical products.

Due to our operations, gasoline vapor containing benzene may be emitted from this facility. Benzene is known to the State of California to cause cancer. Detectable amounts of some chemicals known to the State to cause cancer, birth defects, or other reproductive harm may be found in crude oil, petroleum products or their vapors.

1992 DEC 0 4 1992 ARE J

POWERINE Oil Company

Elo frictal

12354 Lakeland Road, P.O. Box 2108 Santa Fe Springs, California 90670-3857 (310) 944-9861 (310) 944-6111



TLX No: 4720404 A/B Powerne Telecopy No: 944-8522

November 3, 1992

Mr. Yasser Aref
California Environmental Protection Agency
Department of Toxic Substance Control Region 3
Hazardous Materials Specialist
1405 N. San Fernando Blvd, Suite 300
Burbank, California 91504

Re: Request for a variance from the requirement to provide Liability Coverage for Powerine's ISD Facility CAD008383291

Dear Mr. Yasser Aref:

This letter is in response to issues discussed during the Department of Toxic Substance Control (DTSC) site investigation of our refinery on October 22, 1992. In particular you requested that we address the financial assurance requirements for closure, post closure, and liability coverage for our Interim Status Facility, the Alkylation Neutralization Unit (ANU).

As discussed, we have no indication that the soil below our concrete tanks was contaminated by a release of a hazardous waste. Per your suggestion, we propose to provide financial assurance for closure and post closure after the soil investigation is complete. We are also requesting a variance from the requirement to maintain liability coverage. These are further discussed below.

Some of the pertinent facts, including description of the waste being treated and the neutralization process are summarized in Attachment 1, the ISD Fact Sheet.

Closure and Post Closure

Once subsurface soil sampling and analysis is completed, Powerine will:

- revise our closure cost estimate to include the cost associated with soil clean-up;
- prepare a post closure plan and post closure cost estimate (if necessary), and;
- provide financial assurance that we have the resources to close the ISD and satisfy post closure requirements.

POWERINE Oil Company

California Environmental Protection Agency Department of Toxic Substance Control Region 3 November 3, 1992 Page 2

The subsurface soil sampling will not be initiated until Powerine receives preliminary approval of the closure plan provided to DTSC on October 22, 1992.

Request for a Variance From Liability Coverage

Powerine requests a variance from the requirement to maintain liability coverage for sudden accidental occurrences in the amount of 1 million dollars per occurrence and 2 million dollars per year as specified by Section 66265.147. The basis for the variance request is that Powerine is altering the alkylation process such that a hazardous waste will no longer be generated or treated. This will ensure that there could be no accidental occurrence associated with the release of a hazardous waste. The refinery and the ANU will be temporarily shutting down in early November. When (and if) the refinery starts back up (in February of 1993) the inline neutralization will be in full operation.

A description and diagram of the modified in-line neutralization process were mailed to the DTSC on September 1, 1992. A similar though somewhat more comprehensive package was also sent to the South Coast Air Quality Management District (SCAQMD). Based on conversations with the SCAQMD, we anticipate that a Permit to Construct (PTC) will be issued by mid-November 1992.

Should you have any additional questions, please contact Ted Metrose of my staff or myself.

Sincerely,

June M. Christman

Manager - Environmental

Engineering

TKM:aj/DTSC-R3.doc

Enc: Attachment 1 ISD Fact Sheet

cc: Jose Kou (DTSC)

M. Abbasfard (w/attachment)

M. Egner (w/attachment)

W. Chiang (w/attachment)

T. Metrose (w/attachment)

R. Robertson (w/attachment)

File (DTSC-10/23)

ISD Fact Sheet

Owner\Operator: Powerine Oil Company

Address: 12354 Lakeland Road

Santa Fe Springs Ca 90670

Business: Petroleum Refining and Wholesale Marketing

SIC Code: 2911

Generators ID No: CAD 008383291

ISD Facilty Name: Alkylation Neutralization Unit (ANU)

ISD Facility Number: CAD 008383291

ISD Issue Date: April 6,1981

ISD Termination Date: November 8,1992, pursuant to the Health

and Safety Code Section 25200.7(f)

ISD Brief Summary: Elemental neutralizaton of acidic waste in

subsurface concrete tanks

Waste Stream Treated: Alkylation regeneration bottoms,

with a pH of less than 2

RCRA Waste Code: D002

On submitted Part A Part A Summary: Correct

T04 Other treatment Process Code: T01 Tank Treatment

Design Capacity: 19,000 gallons 38,000 gallons

Process Descrip: Concrete walled Concrete tanks

Aerated pits with mechanical

mixers

Est amt treated: 51 tons\year 405 tons\year

ISD Description: The ANU is a small treatment facility, used

to neutralize acidic regeneration bottoms

produced as an undesirable by-product of the refinery's

hydrofluoric alkylation plant (Alky).

Alky regeneration bottoms or "regen bottoms" are a mixture of hydrofluoric acid, water and an organic polymers. Prior to neutralization, regen bottoms have a pH of less than 2 and are

September 1992 F:Alky-fac.wps

classified as a RCRA hazardous waste due to corrosivity. Regen bottoms were purged from the polymer surge drum into a three section underground concrete tank. Hydrated lime and tank mixers were used to keep the pH in the tank above 7. The acidic regen bottoms were neutralized upon being purged into tank. An insoluble salt calcium fluoride is formed. This non-hazardous waste salt sludge is then removed by vacuum truck for offsite disposal.



POWERINE Oil Company

12354 Lakeland Road, P.O. Box 2108 Santa Fe Springs, California 90670-3857 (310) 944-9861 (310) 944-6111



TLX No: 4720404 A/B Powerne Telecopy No: 944-8522

VIA FACSIMILE

October 19, 1992

Guillermo A. Hernandez California Environmental Protection Agency Department of Toxic Substances Control (DTSC) Region 3/Facility Management Branch 1405 N. San Fernando Blvd., Suite 300 Burbank, California 91504

Subject: Review of DTSC Requests Made During Facility Inspection on October 16, 1992

Dear Mr. Hernandez:

Per your facility inspection of October 16, 1992, we understand you need copies or other supporting verification of the following:

- 1) The Interim Status Document (ISD) Waste Analysis Plan, Closure Plan, and Closure Cost Estimate pertaining to the Alkylation Neutralization Unit (ANU);
- 2) Evidence of an agreement by a local hospital to handle Powerine emergencies including planned response to a hazardous waste emergency, particularly from the ANU;
- 3) A list of tank/container inspections excluded recyclable materials and hazardous waste, especially in the ANU;
- 4) List of emergency equipment used to respond to the release of hazardous waste and other related emergencies; -d. k.
- Training records for Judi Gardner and Emergency Response personnel, Bill Ingraham, John Magaña, and Craig Neighbarger. Note: a previous request for documentation of ANU operators training was rescinded;
- 6) Laboratory analysis of wastes and recyclable materials from our profile/characterization notebook marked by Ms. Kathleen Yokota:
- 7) Verification, either directly with or via USA trucking that the ultimate receiver of excluded recyclable materials, principally from California Portland Cement Company is in fact

- read bosness plan or letter

POWERINE Oil Company

California Environmental Protection Agency Department of Toxic Substances Control (DTSC) October 19, 1992 Page 2

receiving the material and managing the material properly.

- Waste profile breakdowns from the Laidlaw in Buttonwillow 8) for the "waste filter" stream;
- Acceptance letter from the Chemical Waste Management 9) facility for the "facility clean up" stream;
- Records of the County Department of Health Services oversight of the recent naphtha line leak on Lakeland Road:

We are now in the process of copying the regulated documentation and securing additional verification. Please contact me should you require any additional information prior to your inspection during the week of October 19, 1992.

Sincerely,

June M. Christman

Manager - Environmental

Engineering

MAW/DTSC1016.doc

cc: M. Gnagy

G. Gardner

J. Magaña


T. Metrose 4

M. Winefield

File

bcc: A. L. Gualtieri

M. Abbasfard



UNIVERSITY OF CALIFORNIA, IRVINE University Extension



This is to certify that

Sudi R. Gardner

has completed requirements for the

CERTIFICATE IN HAZARDOUS MATERIALS MANAGEMENT

MAY 1991

Melvin E. Hall, Dean, University Extension

Date

The Governor's Office of Emergency Services CALIFORNIA SPECIALIZED TRAINING INSTITUTE

San Luis Obispo, California

This is to certify that

Judi R. Bardner

has successfully completed the **Hazardous Materials Course** "FIRST RESPONDER OPERATIONAL"

as defined in California Code Section 1503

and in recognition therefore is awarded 1998his Certificate of Achievement

December 19,

Date

OR8637

Certificate Number

Certified Hours

Director

Certified Instructor

SISHVOEGS SUMMING YOMESTEDIE Inedent Command System Training has completed Jingii IR, Gardiner ও । নত্যসভ তুর্ন নিজ্ঞান্ত্যন্ত্রনাক্ত



OSHA 29 CFR 1910.120 P00911

Certificate of Training

David L. Bales

568-15-9492
has met the 40 hour Initial Training requirement for the Hazardous Waste Operations & Emergency Response

Acknowledgement Expiration: 2/92
Occupational Health & Safety Group, Inc.

POWERINE OIL COMPANY

THIS IS TO CERTIFY THAT

BAHIB II. BAILS

HAS SUCCESSFULLY COMPLETED THE

HAZWOPER COURSE FIRST RESPONDER

as defined in CGG 1503 and 29 CFR 1910.120

6-10-92

DATE

00000

CERTIFICATE NUMBER

SAFETY MANAGEB

*5*30

CERTIFIED INSTRUCTOR

#

POWERINE OIL COMPANY

MEMORANDUM

DATE:

October 19, 1992

TO:

Michael Gnagy

FROM:

Marty Duran

As requested, attached is a copy of the procedures currently being followed when handling work related injuries (Chapter 12 of our Safety Manual).

Page 4, Section III.A., states that when an injury involves a hazardous material, Powerine personnel are instructed to send a copy of the pertinent MSDS to the medical provider along with the "Authorization for Treatment" slip.

As outlined on Page 2, Section I, our medical treating facility is WorkCare or the Emergency Room at Presbyterian Intercommunity Hospital. I've attached a copy of our service agreement.

Let me know if you need more information.

Jul

DEPARTMENT OF TOXIC SUBSTANCES CONTROL (REGION 3) 1405 N. SAN FERNANDO BOULEVARD, SUITE 300 BURBANK, CA 91504 (818) 567-3000



SURVEILLANCE AND COMPLIANCE REPORT HAZARDOUS WASTE GENERATORS/ TRANSPORTERS/TSDFs

(1 h = c == 2	Date of Inspect	tion 10/16/92
CA DO083832		G. HERNANDEZ
EPA I.D. #	Inspector's Name:	
Facility Name/Address:	Mailing Address:	Ownership:
POWERINE OIL CU	SAME	
SANTA FE SPRINGS		
CA 90670		
County L-A.	Type of business: OIL REFINERY	Persons present: R. KOU, T. GUTI ERICE 2,
Contact Person		K. YOKDTA G. HERNANDEZ
MATT WILL TED METROSE		T. METROLE, M. WINEFIELD
Phone # (213) 944-61113		J- GARDIENER
Samples taken? []	Yes (receipt attached)	[×] No
Plan of Correction necessary? []	Yes (Due date:)	[] No
INSPECTION. PURSUANT TO T-27	PROM TEN METROL 1, CCR, SEZTION 66 1L DRYMS IN THE (SIE PORTION OF FACIL OR A PERIOD OF 30 [] Permit [272.1 (c) DTSC
On this date an inspection of your fact Health and Safety Code (H&SC) and collection of samples or other evidence of Section 66272.1, Title 22, California of the H≻ Title 22, California Code of above. These violations relate to the hazardous and extremely hazardous with	Section 66272.1, Title 22, California e, including the taking of photograph Code of Regulations. Specific violati of Regulations; or Code of Federal Re generation, storage, handling, transp	Code of Regulations. The ns, was done under authority ons of one or more Sections agulations, Part 40 are noted
Authorized Representative of Firm*	Authorized State A	gent
Name TEO METROS R	Name Gullerm	"Memo" Herrandez
Title SA KNCR.	TitleA	Zarlas Moterals Specilist
Signature	Signature S	le
Date /9/1c/92	Date/¿	116992
* Signature of firm representative sign	ifies receipt of copy of this form	

REQUESTED COPIES OF JARIOUS BOCUMENTS
TO BE SUPPLIED NEXT WEER (CONTINUATION)
(USDECTION).

POWERINE € CO. →818 567 3027

sthehart A

POWERINE OIL COMPANY

12354 LAKELAND ROAD SANTA FE SPRINGS, CA 90670

TELEPHONE: (310) 944-6111 TELECOPY NO: (310) 944-8522

	9	DTSC 18 567-3		
FROM:	Ed.	Methour		
HISO EN	WHICH B	ACCALLY	70 US 5AYS	FROM FL. DESCRE THAT 100
	EI CONG			
	Beek			
SATISFA S	riod.	See LA	St PAG	- 4

PAGE # 1 OF _____ PAGES.

ROWERINE Oil Company

12354 Lakeland Road, P.O. Box 2108 Santa Fe Springs, California 90670-3857

(310) 944-9861 (310) 944-6111



TLX No: 4720404 A/R Powerne Telecopy No: 944-8522 ;# 2

September 1, 1992

Mr. Jose Kuo Unit Chief Department of Toxic Substance Control DHS - Toxics Substances Control Program 1405 N. San Fernando Blvd. Suite 300 Burbank CA 91504

Notification of termination of use and intent to close the Alky Neutralization Unit, an ISD Facility

Dear Mr. Jose Kuo:

Powerine is hereby intend to close f convert the part (PBR). Pauling p notice: Altho a COLATER than car ... tank have a The abbytish or the state a

e that we have terminated use of and cralization Unit (ANU) which is an cility. We originally planned to an ISD facility to Permit-By-Rule assess an underground tank for PBR, we in small sections of the tank floor. compromise the integrity of the tank, we cop using the tank and close the ANU rather er PBR. The non-hazardous contents of the removed and disposed at a Class II landfill. removed and disposed at a Class II landfill. will be altered such that we no longer generate - waste.

\$ 1 to 100 opy of your most recent Closure and Partial Closure ent so that we may revise our existing closure plan, · · · ilangay •

The attached report provides a synopsis of the current regulatory and Revalcal status of the ANU. It also contains an update on the progress that has been made towards terminating use of the ANU by altering the regeneration process.

Should you have any questions please contact Ted Metrose of my staff at 310/944-6111.

Sincerely,

June M. Christman

Manager - Environmental

Engineering

TKM:alky-clo.txt

Termination of Use and Intent to Close the Alkylation Neutralization Unit

Description of Curtailed ANU Operation

The Alky Neutralization Unit (ANU) was used to neutralize acidic alkylation (alky) regeneration bottoms which is a mixture of acid, water and an organic polymer referred to as "tar". The acid and water form an azeotrope referred to as Constant Boiling Material which will not vaporize under atmospheric conditions. regeneration bottoms have a pH of less than 2. Regeneration bottoms were purged from the polymer surge drum into an underground concrete tank. Hydrated lime and tank mixers were used to keep the pH in the tank above 7. The acidic regeneration bottoms were neutralized upon being purged into the tank and an insoluble calcium fluoride salt was formed. This non-hazardous waste sludge is then removed by vacuum truck for off-site disposal. Powerine has characterized the neutralized regeneration bottoms as nonhazardous based on comprehensive analytical data presented as Attachment 1.

Regulatory Background

Prior to neutralization, the regeneration bottoms with a pH of less than 2 meet the federal definition of a RCRA hazardous waste due to corrosivity. However, a RCRA permit is not required to treat the regeneration bottoms because elementary neutralization is exempt pursuant to the Code of Federal Regulations Part 40 Section 264.1(6). The EPA confirmed the exemption in a letter to Powerine Oil dated June 10, 1981, (Attachment 2) which stated that a RCRA permit was not required. However, since the State does not have a similar exemption, Department of Health Services (DHS) Department of Toxic Substances Control (DTSC) issued an Interim Status Document (ISD) (number CAD008383291) as a temporary operating permit on April 6, 1' This permit is presented as Attachment 3.

The (ISD) will terminate on November 8, 1992, pursuant to the Health and Safety Code Section 25200.7(f). To maintain a valid operating permit, Powerine originally intended to convert the permit stands of the ANU from and an ISD facility to a fixed treatment it (FTU) operating pursuant to Permit-By Rule (PBR). In a letter dated January 30, 1992 (Attachment 4) Powerine sent a Notification of Intent to operate pursuant to PBR to the DTSC.

Results of Tank Inspect Alassessment

To satisfy the requirements for operation pursuant to PBR, Powerine prepared to conduct %h assessment of underground tanks. ocording to the Castfornia Code of Regulations (CCR) Section 57450.2(b)(3)(1), existing tanks operating pursuant to PBR must be assessed according to the criteria specified in 66265.191(a). The neutralized (non-hazardous) contents of the tank The tank was hydroblasted to remove the calcium were removed. fluoride-lime sludge from the tank walls and bottom, to facilitate Visual inspection of the tank in June of 1992 the assessment indicated that there were small sections of concrete erosion such

that steel reinforcement bars (re-bar) were exposed. Several pictures of the tank are presented as Attachment 5.

While there was superficial erosion of the tank, there was no evidence that acidic regeneration bottoms had been released. In fact, the tank was observed to contain free standing water (from the hydroblasting). While chemical erosion can not be eliminated as a contributing factor to degradation of the tank bottom, physical abrasion caused by eddy currents established by the mixers probably played a larger role. The tank bottom erosion was located in the center of the tanks directly under the tank mixers. re-bar showed no signs of excessive corrosion. The exposed indicators support the conclusion that physical abrasion caused the erosion. Strict operating procedures ensure that pH of the tank contents is above $\bar{7}$.

Y while there is no evidence to suggest that there was a release of a hazardous waste, we believe that continued extended use of the underground tank without repairs is imprudent. Consequently additional flow of acidic regeneration bottoms into the tank has been terminated. Powerine has decided to close the tank and the entire alky neutralization unit.

<u>Interim Measures:</u>

Before a permanent process change to eliminate the generation of a hazardous waste can be engineered and installed, Powerine has taken certain interim measures.

These interim measures include piping and operational changes. Flow of the regeneration bottoms from the polymer surge drum have been hard-piped to an above-ground steel Baker tank. Lime is mixed with water in a small (40 bbl) temporary tank, located at ground level for easy and safe access by operating personnel. This lime solution is then pumped into the Baker tank to maintain a pH of 7 or higher.

This interim method of neutralizing the regeneration bottoms will continue until the permanent process change described below can be implemented.

Permanent Process Change: Eliminate Hazardous Waste Generation and Treatment

The regeneration process that occurs within the alkylation unit will be altered such that hazardous waste is no longer produced. Enclosed as Attachment 6 is a diagram of the new process which provides that neutralization of the regeneration bottoms is done as part of the process. Acidic regeneration bottoms do not exit the regeneration section of the Alkylation unit. Further, no subsurface tanks are employed in the new process. Finally the amount of non-hazardous sludge generation is expected to decline by 30% because; in-line neutralization of the regeneration bottoms will be more effective than neutralization in the ANU.

Closure

Powerine intends to comply with the applicable requirements for closure and post closure as specified by:

- Applicable sections of the specific ISD (CAD0083291) for the ANU
- 2. Applicable sections of Article 7 and Article 8 of Division 4.5 of Title 22 of the CCR which regulates all ISD facilities
- 3. Article 10 and more specifically Section 66265.197 Which defines the closure and post closure for ISD facilities consisting of tanks.

However the DTSC should recognize that many of these closure and post closure requirements will have only limited applicability because 1.) the material that actually was stored in the tank is a non-hazardous waste and 2.) the sludge has already been removed from the pit. As such the requirement to remove all of the hazardous waste and the requirement that Powerine maintain the financial responsibility for doing so, is moot.

Attachment 1: Alky sludge characterization Attachment 2: RCRA exemption letter from EPA

Attachment 3: Cover Page of Interim Status Document

Attachment 4: Letter Notification of Intent to Operate

pursuant to PBR

Attachment 5: Picture of Underground Tanks

Attachment 6: Diagram of In-Process Neutralization System



ATTRCHMENT

Slubje

ASSOCIATED LABORATORIES

806 North Batavia - Orange, California 92668 - 714/771-6800

FAX 714/508-1209

CLIENT .

Jamos from Baker turks

(3877)

LAB NO.

G15146

REPORTED.

09/13/91

SAMPLE

Sludge (Hydrofluoric Acid w/Lime) RECEIVED

08/27/91

IDENTIFICATION

Powerine Oil Co.

Date Collected 08/25/91 @ 12:30 pm

BASED ON SAMPLE

As Submitted

	LIM	tts '	Alky (Baker Tank)
CAM INORGANICS	TTLC	STLC	TILC
	(mg/kg)	(mg/1)	(mg/kg)
Antimony	500	15	12.5
Arsenic	500	5.0	2.90
Barium	10,000	100	62.9
Beryllium	75	0.75	ND< 0.4
Cadmium	100	1.0	ND< 0.4
Chromium, Hex.	500	5	ND< 1
Chromium, Total	2,500	560	4.12
Cobalt	8,000	80	1.72
Copper	2,500	25	5.48
Fluoride	18,000	180	461
Lead	1,000	5.0	ND< 5
Mercury	20	0.2	ND< 0.08
Molybdenum	3,500	350	5.09
Nickel	2,000	20	3.96
Selenium	100	1.0	ND< 1
Silver	500	5	1.40
Thallium	700	7.0	ND< 1
Vanadium	2,400	24	5,48
Zino	5,000	250	7.79

Cont. on page 2

ATTACHMENT 1-B

Client: Waste Materials Management

Lab No.: G15146

September	13,	1991

TCLP EXTRATION - SEMIVOLA	TILES	thod	(mg Resu	<u>lts</u> /1)
o-Cresol 200 m-Cresol 200 p-Cresol 200 Cresol 200 1,4-Dichlorobensene 2,4-Dinitrotoluene	0 8 0 8 1 0 8 1 5	270 270 270 270 3270 3270 3270	ND< ND< ND< ND< ND<	0.8 0.8 0.8 0.8
Hexachloro-1-3- butadiene Hexachloroethane Nitrobenzene	3.0	9270 8270 8270 8270 8270 8270 8270	ND<	0.8 0.8 4 4

TCLP EXTRACTION - VOLATILES

	Limits (mg/l)	Method	Results (mg/l)
Benzene	0.5	8240	ND<0.005
Carbon Tetrachloride	0.5	8240	ND<0.005
Chlorobenzene	100.0	8240	ND<0.005
Chloroform	6.0	8240	ND<0.005
1,2-Dichloroethane	0.5	8240	ND<0.005
1,1-Dichloroethylene	0.7	8240	ND<0.005
Methyl-ethyl-ketone	200.0	8240	ND<0.03
Tetrachloroethylene	0.7	8240	ND<0.005
Trichlorogthylene	0.5	8240 .	ND<0.005
Vinyl Chloride	0.25	8240	ND<0.01

ASSOCIATED LABORATORIES, by:

Vice President

ESB/ql

NOTE: Unless notified in writing, all samples will be discarded by appropriate disposal protocol 30 days

ATTACHMENT

REPORT OF LABORATORY ANALYSIS

Powerine 011

surve

April 20, 1992

PACE Project Number: 7204175

12354 Lakeland Rd. Santa Fe Springs, CA 90670

Attn: Ms. Judi Gardener

Client Reference: Waste Water

PACE Sample Number: Date Collected: Date Received: Client Sample ID: Parameter

linits MDL 04/11/92 Waste Water

04/10/92

75 0074591

SUBCONTRACT ANALYSIS

INDIVIDUAL PARAMETERS Acute Aquatic Toxicity (Bioassay)

mg/L

LC50 > 500 .

MDL

Method Detection Limit

These data have been reviewed and are approved for release.

Kenneth D. Faust.

Southern California Regional Director

ATTALAMENT



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

295 Fremont Street 28 San Francisco, Ca. 94105

Mr. T. L. Antonoplos Powerine Oil Co. 12354 Lakeland Road Santa Fe Springs, CA 90670

Santa Fe Springs Facility (EPA ID No. CAD008383291)

Dear Mr. Antonoplos:

The Environmental Protection Agency (EPA) has received Part A of a permit application pursuant to Section 3005 of the Resource Conservation and Recovery Act (RCRA) for the facility referenced above. The application does not demonstrate that the facility is one which is required to have a permit under Section 3005 of RCRA.

On November 17, 1980, EPA granted an exclusion from individual RCRA permit requirements to facilities which are used for neutralizing wastes which are hazardous only because they exhibit the corrosivity characteristic defined in 40 CFR 261.22, if the neutralization process takes place in a tank, container, transport vehicle, or vessel. It appears from the Part A permit application that the subject facility comes under this exclusion.

For this reason, stated above, we are returning your permit application. If the facility referenced above is in fact one which is required to have a permit under RCRA, you must resubmit this application within thirty days. A cover letter describing the reason(s) for requiring a permit should accompany your application.

If you have any questions in this regard, please contact me or my staff at (415) 556-1047.

Sincerely,

William D. Wilson

Hazardous Materials Branch

Enclosure

STATE OF CALIFORNIA-HEALTH AND WELFARL

ENCY

EDMUND G. BROWN JR., Governor

DEPARTMENT OF HEALTH SERVICES

714/744 P-STREET ...

BACRAMINTO, CA 95814

ACAD B. SKOWN JR., Governor

INTERIM STATUS DOCUMENT

Number: CAD 008383291

Effective Date: April 6, 1981

) Te.

ATTA CHMENT

Operator: Powerine Oil Company

12354 Lakeland Road

Los Angeles County

Facility: Powerine Oil Company

12354 Lakeland Road

Santa Fe Springs, CA 90670

Santa Fe Springs, CA 90670)

Pursuant to Section 25200.5 of the California Health and Safety Code, this Interim Status Document is hereby granted to Powerine Oil Company subject to the conditions set forth in Attachment A which by this reference is incorporated herein.

Harvey F Collins, Ph.D., Chief Environmental Health Branch

THE MHOATE AT



POWERINE Oil Company

12354 Lakeland Road, P.O. Box 2108 Santa Fe Springs, California 90670

(213) 944-9861 (213) 944-6111



TLX No: 4720404 A/B Powerne Telecopy No: 944-8522

January 30, 1992

Department of Toxics Substance Control Surveillance and Enforcement Branch P.O. Box 806 Sacramento, California 95812-0806

Initial Notification for Permit-by-Rule Operation of the Alky Neutralization Unit

Dear Sirs:

Enclosed as Attachment 1 is an initial notification of intent to operate a small treatment facility at our Santa Fe Springs refinery, under Permit-by-Rule (PBR) for fixed treatment units pursuant to Title 22, California Code of Regulations, Section The refinery is currently operating a 67450.2(b). neutralization (treatment) facility at the refinery under authority of an Interim Status Document (ISD) (CAD008383291) issued by the Department of Health Services on April 6, 1981. The ISD will terminate on November 8, 1992, pursuant to the Health and Safety Code Section 25200.7(f). Consequently, Powerine wishes to convert the permit status of the Alky Neutralization Unit from a ISD facility to a PBR fixed treatment unit.

As a precondition of PBR status (Section 66270.60(g)(2)), Powerine hereby withdrawals a previous request to become a permitted facility under the expectation that the treatment facility will qualify for PBR. (A similar withdrawal request has been forwarded to the Los Angeles Regional Office.)

Please note that current treatment facility is not required to have a RCRA permit because neutralization of a hazardous waste with a pH less than 2 is exempt pursuant to 40 CFR 264.2(g)(6) and This is verified by the in a letter dated 265.1(c)(10). 6/10/81 enclosed as Attachment 2. Consequently, neutralization of acidic hazardous waste will meet the requirement specified in Section 67450.11 that treatment of the waste is not regulated under RCRA.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

75 Hawthorne Street San Francisco, Ca. 94105

1 4 JAN 1991

RECEIVED

JAN 1 8 1991

Ans'd....

Donald DuRivage
Powerine Oil Company
12354 Lakeland Road
P. O. Box 2108
Sante Fe Springs, CA 90670-9883

Dear Mr. DuRivage:

A RCRA Compliance Evaluation Inspection was conducted at Powerine Oil Company on July 30, 1990. The inspectors representing EPA found instances of RCRA non-compliance during this on-site inspection and their report was forwarded to you for response. The written responses dated 11/28/90 and 12/20/90 adequately address the violations.

Therefore, the facility operated under EPA identification number CAD008383291 is considered to be in compliance with the RCRA regulations cited as violations during the 1990 inspection.

For any questions regarding this letter, please contact Jean Daniel at (415) 744-2128.

Thank you for your cooperation.


Sincerely,

Karen Schwinn

Chief,

Waste Compliance Branch

cc: June Christman, Manager, Environmental Engineering Scott Simpson, CA DHS/TSCP, Region 3 Don Johnson, CA DHS/TSCP, HQ Erlinda Maclintow, HazConPqm, LA County



etio ley

10 13/97
Department of Toxic Substances Control

HAZARD APPRAISAL AND RECOGNITION PLAN PRESITE VISIT FORM

SECTION A. FIELD TEAM Prepared By: Golfern Mono" Herrandez Date: 13-13-92	SECTION E. BASIC INFORMATION ON POTENTIAL HAZARDS (Attach copies of HARP Chemical Data Sheets or other appropriate information as suggested in instructions.)
Phone: (818) 567- 3074	SECTION F. EXPOSURE CONTROL METHODS
Responsibility	☐ Engineering
Memo Herminder IMB Led Field Staff The Holem Y, Kota FMB J. H. Support Rubert Kor FMB Photography Autority Korta FMB Photography The Support	Describe: No. 2 Uninger Wide St. coms, follow all 1 1114 I If to them Like St. cons. A wid for period the of Exposite. Exposite to the Network of
Tina Crutienes FMB 1 Sander	the complexed.
5. Strac Guerray 1715	,
0	SECTION G. REQUIRED PERSONAL PROTECTIVE EQUIRMENT
SECTION B. SITE DESCRIPTION	Level of Protection: \BB \BC \\ \D \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\
Site Name: Pobleciand Oil Co	Glove(s): Outer = O, Inner = I Cotton/Vinyl Cloth Coveralls
PCA No.: Project # WP WP	Silver Shield/4H Tyvek
Address	Neoprene P. E. Tyvek
City: 50-14 76 3000 State: 6/1 Zip: 70 670	Nitrile Saranex Sande in level
NOTE: Attach Map of Site and Directions to Hospital	PVC/Monkey Glip PVC
Contact Person: 6. 4. Peter Son	Grip Glove/Kevlar Baracade/Chemtuff
Type of Operation/Waste Stream (Describe):force.re . It f res	Viton
Crite oil int Metro Vilous grades	Respirator: A/P Cartridge:
OF gesolve, diesel, and evelon leels	SCBA Escape (ELSA – 5 Min.)
Purpose of Visit (Describe):	Other Safety Gear:
Conflaint - alleging Ment heatling	☐ Binoculars ☐ Hearing Protection Plugs ☐ Muff ☐
of Hydro Floric act in pils	☐ Boot Covers ☐ Safety Vest
Site Visit Date(s): 13-16-97	Boots Two-Way Communication Kit
Estimated Time on Site: Hours/Day Days	Eye Protection Other:
Nearest Hospital and Address: 12500 S Flo X/L AVE	Hard Hats
toiser Hospital Norwelk	SECTION H. SURVEY EQUIPMENT
Phone No.: (713) 420 - 4321	Combustible Gas/Oxygen Meter
SECTION C. NUMBER OF SAMPLES TO BE COLLECTED	Photoionization Detector Probe:
Air Surface Impoundment	☐ Organic Vapor Analyzer (OVA) ☐ TLV Sniffer
Drums(s) Surface Water	Drager Tubes (Specify:)
Groundwater Tank(s)	pH Meter/Paper
Soil/Sediment Waste/Sludge	Safety Vest Proposed work
Sump(Pi) H F Other	Two-Way Communication Kit
SECTION D. POTENTIAL HAZARDS	Binoculars Radiation Meter (Victoreen 400)
Chemical Hazards 2. Physical Hazards	☐ Aerosol/Particle Monitor ✓ Other (Specify: NOISE presented)
<u> </u>	Other (Specify: NOISE mentles personal)
Corrosives 5-11-11 AC. (1002) HF (Source:)	SECTION I. OTHER HYGIENE AND SAFETY EQUIPMENT
Developmental Health Heat or Cold Stress (Expected	
Hazards (Teratogen)° F)	On Site Bring
Dusts Machinery/Construction	Canopy/Tarp/Umbrella Drinking Water
Explosives Noise (Source/Decibels)/ Lineary	Drinking Water Shower/Eye Wash
Flammables Oxygen Deficiency	Fire Extinguisher
☐ Inorganic Vapors Gases ☐ Radioactive Materials ☐	□ □ First Aid Kit (Check Ca)
✓ Metals 166 bills Contra Contra Unknown/Other	Plastic Sheeting/Buckets/Bags
☐ Oxidizers 3. ☐ Biohazards ☐ PCBs 4. ☑ Other (Specify):	Portable Toilets
Pesticides	□ Washing Facilities
Reproductive Health Hazards	SECTION J. PERSONAL MONITORING
Skin Absorption	Heart Rate Oral Temperature
Solvents (bloggete) (1001)	Do You Need Industrial Hygiene Monitoring? Yes No
(Use this space to describe hazards)	If Yes, What Type? Noise Air Other (Specify:
Simply will be done of the Highertonic	
Acid using the methods:	SECTION K.) REVIEW/APPROVAL
1) Spijot or Velve (will be collected	(Xort Von) (12/12) 1x/14/07
by facility prisonnell.	Health and Safety Unit (Review)
- 3) USIN JOY Sampler - 10 Saigler	1 100
- will Same And Ad it you'll deared	160 Thaman 10-13-72
Sole Sir to Stead and Smiller	Supervisor (Approval) Date
DTSC 1031 (5/92) (or be done - proposably 2 test	
(Formerly DHS 8299 A) (Original — Exposure Records Yellow — Site File	Pink — Department Goldenrod — Supervisor)
trum edge of Pit.	

' An inspection has been made in the hazardous waste accumulation area and the hazardous materials area for Powerine Oil Company located at 12354 Lakeland Road, Santa Fe Springs, California.

DIV: Environmental

UNIT: Hazardous Waste Accumulation Area TECH SIGNATURE: David Bales DATE: 10-9-92

Equip. No.	Location	Туре	Chrg. Date	Remarks
HWAA- D1	(North West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D2	(North East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
-WAA- D3	(South West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PAT
	(South East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D5	(On North fence line)	Dry-Chem	8-14-92	1900 PSI
HWAA- SS1	Safety Shower	WATER	10-9-92	FLUSHED LINES

		Date '	Initials
1.	I have checked all drums containing hazardous waste and found them to be in satisfactory condition.	10-9-92	D.B.
2.	If condition of drums were not acceptable, what action was taken?	10-9-92	D.B.
3.	I have checked all hazardous material drums and found all drums to be in satisfactory condition.	10-9-92	D.B.
4.	If condition of drums were not acceptable, what action was taken?	10-9-9Z	D. B.

Person	notified:	1	Rev.	5/20/91

COMMENTS: NON DEPOSIT DRUMS AND POLLYS BEING REMOVED FROM YARD.

An inspection has been made in the hazardous waste accumulation area and the hazardous materials area for Powerine Oil Company located at 12354 Lakeland Road, Santa Fe Springs, California.

DIV: Environmental
UNIT: Hazardous Waste Accumulation Area TECH SIGNATURE:

TECH SIGNATURE: David Bales

DATE: 10-2-92

				
Equip. No.	Location	Туре	Chrg. Date	Remarks
HWAA- D1	(North West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D2	(North East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
WAA- D3	(South West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PS
	(South East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D5	(On North fence line)	Dry-Chem	8-14-92	1900 PSI
HWAA- SS1	Safety Shower	WATER	10-2-92	FLUSHED LINES

		Date	Initials
1.	I have checked all drums containing hazardous waste and found them to be in satisfactory condition.	10-2-92	D.B.
2.	If condition of drums were not acceptable, what action was taken?	10-2-92	D.B.
3.	I have checked all hazardous material drums and found all drums to be in satisfactory condition.	10-2-92	D.B.
4.	If condition of drums were not acceptable, what action was taken?	10-2-92	D. B.

Person	notified:	
Person	notified:	

Rev. 5/20/91

COMMENTS: CLEARING OUT JUNKER AND PLOY DRUMS.

'An inspection has been made in the hazardous waste accumulation area and the hazardous materials area for Powerine Oil Company located at 12354 Lakeland Road, Santa Fe Springs, California.

DIV: Environmental

UNIT: Hazardous Waste Accumulation Area TECH SIGNATURE: David Bales 9-23-92 DATE:

Equip. No.	Location	Туре	Chrg. Date	Remarks
HWAA- D1	(North West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D2	(North East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
WAA- D3	(South West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PS
#AA- D4	(South East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D5	(On North fence line)	Dry-Chem	8-14-92	1900 PSI
HWAA- SS1	Safety Shower	WATER	9-23-92	FLUSHED LINES

France		Date	Initials
1.	I have checked all drums containing hazardous waste and found them to be in satisfactory condition.	9-23-92	D.B.
2.	If condition of drums were not acceptable, what action was taken?	9-23-92	D.B.
3.	I have checked all hazardous material drums and found all drums to be in satisfactory condition.	9-23-92	D.B.
4.	If condition of drums were not acceptable, what action was taken?	9-23-92	D. B.

Rev. 5/20/91

COMMENTS: PUTTING ALL REMAINING DRUMS IN ORDER.

An inspection has been made in the hazardous waste accumulation area and the hazardous materials area for Powerine Oil Company located at 12354 Lakeland Road, Santa Fe Springs, California.

DIV: Environmental
UNIT: Hazardous Waste Accumulation Area TECH SIGNATURE: David Bales
DATE: 9-18-92

Equip. No.	Location	Туре	Chrg. Date	Remarks
HWAA- D1	(North West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D2	(North East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
-waa- D3	(South West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
#AA- D4	(South East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D5	(On North fence line)	Dry-Chem	8-14-92	1900 PSI
HWAA- SS1	Safety Shower	WATER	9-18-92	FLUSHED LINES

		Date	Initials
1.	I have checked all drums containing hazardous waste and found them to be in satisfactory condition.	9-18-92	D.B.
2.	If condition of drums were not acceptable, what action was taken?	9-18-92	D.B.
3.	I have checked all hazardous material drums and found all drums to be in satisfactory condition.	9-14-92	D.B.
4.	If condition of drums were not acceptable, what action was taken?	9-18-92	D. B.

Person	notified:	

Rev. 5/20/91

An inspection has been made in the hazardous waste accumulation area and the hazardous materials area for Powerine Oil Company located at 12354 Lakeland Road, Santa Fe Springs, California.

DIV: Environmental
UNIT: Hazardous Waste Accumulation Area TECH SIGNATURE: David Bules
DATE: 9-11-92

Equip. No.	Location	Туре	Chrg. Date	Remarks ,
HWAA- D1	(North West Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D2	(North East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
-'WAA- D3	(South West Center)			EXTINGUISHER IN GREEN 195 PSI
#AA- D4	(South East Center)	Dry-Chem	8-14-92	EXTINGUISHER IN GREEN 195 PSI
HWAA- D5	(On North fence line)			1900 PSI
HWAA- SS1	Safety Shower	WATER	9-11-92	FLUSHED LINES

	·	Date '	Initials
1.	I have checked all drums containing hazardous waste and found them to be in satisfactory condition.	9-11-92	D.B.
2.	If condition of drums were not acceptable, what action was taken?	9-11-92	D.B.
3.	I have checked all hazardous material drums and found all drums to be in satisfactory condition.	9-11-92	D.B.
4.	If condition of drums were not acceptable, what action was taken?	9-11-92	D. B.

son notified:
son notified:

Rev. 5/20/91

COMMENTS: CALLING VENDORS OUT TO PICK-UP DEPOSIT DRUMS.

An inspection has been made in the hazardous waste accumulation area and the hazardous materials area for Powerine Oil Company located at 12354 Lakeland Road, Santa Fe Springs, California.

DIV: Environmental
UNIT: Hazardous Waste Accumulation Area TECH SIGNATURE: David Bales

DATE: 9-4-92

Equip. No. Location Chrq. Date Remarks Type 8-14-92 EXTINGUISHER IN GREEN 195 PSI Dry-Chem HWAA- D1 (North West Center) 8-14-92 FXTINGUISHER IN GREEN 195 Dry-Chem HWAA- D2 (North East Center) 8-14-92 EXTINGUISHER IN GREEN 195 "WAA- D3 (South West Center) Dry-Chem 8-14-92 EXTINGUISHER IN GREEN 195 PSI Dry-Chem .#AA- D4 (South East Center) 8-14-92 1900 PSI HWAA- D5 (On North fence line) Dry-Chem

9-4-92 FLUSHED LINES

		Date	Initials
1.	I have checked all drums containing hazardous waste and found them to be in satisfactory condition.	9-4-92	D.B.
2.	If condition of drums were not acceptable, what action was taken?	9-4-92	D.B.
3.	I have checked all hazardous material drums and found all drums to be in satisfactory condition.	9-4-92	D.B.
4.	If condition of drums were not acceptable, what action was taken?	9-4-92	D. B.

WATER

Person notified:	
------------------	--

HWAA- SS1

Safety Shower

Rev. 5/20/91

POWERINE OIL COMPANY

Closure Plan and Closure Cost Estimate for the Alkylation Neutralization Unit

ISD No. CAD008383291

1.0 INTRODUCTION

This document is Powerine Oil Company's plan for closing the Alky Neutralization Unit (ANU) which was previously operated under the authority of an Interim Status Document (ISD) (CAD008383291) issued by the Department of Health Services. The ANU is located at Powerine's refinery at 12354 Lakeland Road in Santa Fe Springs, California. The ANU is a small treatment facility, used to neutralize acidic regeneration bottoms produced as undesirable by-product of the refinery's hydrofluoric alkylization plant (Alky).

In a letter dated September 1,1992, Powerine advised the Department of Toxic Substance Control (DTSC) of the following:

- Use of the ANU subsurface concrete tanks was terminated in early June 1992.
- The non-hazardous contents of the ANU tanks had been removed and disposed at a Class II disposal facility.
- An interim procedure for neutralizing acid regeneration bottoms would be implemented until capital improvements are made to the alkylation process that would prevent the generation and treatment of hazardous waste.
- As indicated above, the alkylation process would be altered by installing an in-line neutralization system that would prevent generation of a hazardous waste.
- Powerine intends to close the ISD facility.

Powerine intends to comply with the applicable requirements for closure and post closure as specified by:

- 1. Applicable sections of the specific ISD for the ANU
- Applicable sections of Article 22 and Article 23 of Division 4.5 of Title 22 of the CCR which regulates all TSD facilities
- Article 10 and more specifically Section 66265.197 which defines the closure and post closure for ISD facilities consisting of tanks.

However, DTSC should recognize that many of these closure and post closure requirements have only limited applicability because:

- the material that actually was stored in the subsurface concrete tank is a non-hazardous waste and
- the sludge has already been removed from the subsurface tanks.

As such, the requirement to remove all of the hazardous waste and the requirement that Powerine maintain the financial responsibility for doing so, is moot.


2.0 Closure Performance Standard (Section 66265.111)

Powerine will close the ANU in a manner that:

- ensures the safety of all employees and contractors during actual closure.
- minimizes the need for further maintenance.
- controls, minimizes or eliminates, to the extent necessary to protect human health and the environment, post-closure escape of hazardous waste, hazardous waste constituents, leachate, contaminated rainfall or waste decomposition products to the ground or surface waters or to the atmosphere.

3.0 Closure Plan and Amendment of the Plan (Section 66265.112)

This plan addresses closure of the ANU as it originally operated and as it has operated during the interim period. Submittal of the plan to DTSC has been deferred based on conversation Mr.Andy Bajwa of DTSC staff. Mr Bajwa instructed Powerine to submit the aformentioned termination of use and intent to close letter of



September 1,1992 and await for additional guidance on preparation of the plan. This plan has been prepared prior to receipt of that guidance.

This plan will be revised upon receipt of the guidance document to the extent necessary. It will be further revised as necessary to complete closure.

3.1 Closure Notification and Plan Submittal

Powerine provided to the district notification of intent to close the ISD on September 1,1992. Powerine is obligated to submit a closure plan to the DTSC by November 23,1992. This date is established by Section 66265,118(e)(1) which mandates that the closure plan be submitted no later than 15 days after termination of the ISD. The ISD for Powerine's ANU terminates November 8,1992 pursuant to the Health and Safety Code Section 25200.7(f).

On this schedule, if Powerine were to notify the DTSC and provide a copy of the closure plan on November 23,1992, then closure could begin as early as May 23,1993. But since the plan has not yet been approved the closure probably will not be initiated until the fall of 1993. Powerine wants to close the ANU as soon as possible because:

- Powerine no longer wants to operate a treatment facility nor pay annual fees associated with such an operation and
- Community relations will be improved by eliminating what may be perceived as a public risk.

Powerine will provide all support necessary to accelerate the closure plan approval process.

3.2 Overview of Closure Plan

Gernerally closure of the ANU will be implemented by following the steps:

1. Without structurally damaging the north section of the tank, soil samples will be taken from below the East and West sections of the tank. The north section of the tank will be used to collect washdown water and storm runoff so it must remain structurally sound. The soils samples will be analyzed for the contamination that could be associated with release of the acidic regeneration bottoms. Soil sampling will be deepened as necessary to determine the extent of the contamination if any.

- 2. If soil sampling indicates that there has not been a hazardous waste release then the East and West portion of the Alky Neutralization will be backfilled with clean fill. Powerine will request closure of the ANU in-place, without additional excavation of the concrete structure.
- 3. If the soil sampling indicates that there has been a hazardous release which can not safely be left in place and which can not be remediated institu, then Powerine will request a partial closure of the ANU. The concrete subsurface tank will be backfilled with clean fill, to assure the DTSC that the susbsurface neutralization has been permantely terminated. Soil contamination below the tank will be addressed if the alklylation plant is replaced or 180 days after Powerine or a subsequent owner determines that the existing refinery is no longer a viable business and must be permanently decommissioned, whichever is first. Under no circumstances shall remediation of soil contaminated by release of a hazardous wastes from the ANU be deemed complete wihout first obtaining DTSC approval.
- 4. The steel pipes from the polymer surge drum to the interim non-hazardous surface tanks will be decontaminated by flushing them with a basic solution. Decontamination will not be deemed complete until the pipe effluent is pH 7 or greater. The decontaminated pipes will be discarded as scrap metal.

3.3 Maximum Waste Inventory and Disposal Thereof

The maximum volume of acidic regeneration bottoms that can be stored in the lines from the polymer surge drum to the above ground tank or approximately . bbls. In the event that Powerine's neutralization facility is inoperable, a third party contractor will be hired to perform much the same tasks. Offsite transportation and disposal of a highly acidic waste is considered unsafe and without merit. The neutralized material will be disposed at an approved non-hazardous facility.

The <u>neutralized</u> regeneration bottoms previously stored in the subsurface concrete tanks and currently stored in the above ground steel tank are non-hazardous. These sludges are not subject to the inventory estimate of section 66265.112.

3.4 Soil Sampling and Analysis

Two (2) 6" borings will be drilled through and 10 feet below the bottom of the existing subsurface concrete tanks using a powered

Powerine Oil Company ISD Closure

auger. Soil samples will be taken on at 1, 5 and 10 feet and analyzed as specified below. Soils encountered in the subsurface will be logged and described according to the Unified Soil Classification System. Soil moisture and other significant characteristics will be noted on the boring logs.

All augers will be thoroughly steam cleaned before drilling each boring. No drilling additives will be used. Upon completion, each borehole will be backfilled from the bottom to within one-half foot of the ground surface with bentonite grout. The top of the boreholes will be capped with concrete, flush to surface of the ANU tank.

Soil samples will be collected using a hand sampler as described in the USHMG, Soil Sampling. All sampling equipment will be thoroughly cleaned before each sample is collected. The cleaning procedure will include a tap water rinse, a thorough scrubbing with tap water and non-phosphate detergent, a second tap water rinse, and a final rinse using distilled water.

The samples will be screened at the drill site for volatile organic vapors using a portable photoionization detector (PID), such as the HNu Model PI 101. PID readings will be recorded on the boring logs. All samples will be capped with a teflon liner and a plastic cap and sealed with electrical tape. Identification labels will be placed on the samples and will indicate the borehole number, date and time of sampling, depth and name of the drilling supervisor. All samples will be stored on "blue ice" and delivered to a California-certified, analytical laboratory within 24 hours of collection. Standard chain-of-custody procedures will be strictly followed in submitting the samples for laboratory analysis.

The soil samples will be analyzed for pH, and fluoride content.

The following information will be presented in the soil assessment report:

- Site history, including a description of the current and previous site usage along with a desciption of the materials historically contained in the tanks;
- Site geology based on information contained in published and unpublished technical reports and on data derived from a soil borings to be drilled;
- Site hydrogeology based primarily on information contained in published and unpublished technical reports;
- Site layout which will be shown on a scaled plot plan; and

 Sample protocol, including soil sample analysis results, date of sampling, and chain-of-custody documentation.

3.5 Soil Remediation/Disposal Contingency

Should the results of soils analysis indicate that a hazardous release has occurred, at concentration that are potentially harmful to the environment Powerine will submit a soil remediation and disposal plan for approval by DTSC.

4.0 Certification of Closure (Section 66265.115)

When closure is completed, Powerine Oil Company (POC) shall submit to the DTSC and CRWQCB certification by POC and by an independent, qualified professional engineer, registered in California, that the facility will be closed in accordance with the specifications in the approved closure plan.

5.0 CLOSURE SCHEDULE

The schedule for closure is as follows:

Activity	Days
Submittal and DTSC approval of the Closure Plan	Start
Notification to Begin Closure	180
Public Notification and Hearing (Days list as not appicable because this step would be conducted during the 180 notification period.	NA
Drill and log 2 boreholes	30
Analyze soil samples	30
Prepare soil assessment report	30
Backfill subsurface concrete tanks	10
Removal and neutralization of alky regeneration bottoms from pipes. Decontamination of pipes. No additional time required.	NA
Preparation of closure certification report	21
Total Time required from date of notification	121

Powerine Oil Company ISD Closure

As can be noted from the above schedule, if there is no subsurface soil contamination caused by the release of a hazardouds waste from the ISD then Closure will easily be completed within 180 days as required.

6.0 CLOSURE COST ESTIMATE AND FINANACIAL ASSURANCE

The estimated closure costs are presented on Table 1. Given the relative small cost of closure in comparison to Powerine's operating revenues no financial assurance mechanism was provided.

7.0 Post Closure Care and Use of Property (Section 66265.120)

No hazardous waste from the ANU will remain on site after its closure. Therefore the directives of Section 66265.120 in the CCR do not pertain to this treatment facility. Soil contamination may trigger additional post closure monitoring requirement.

TKM:aj/alky-cp.wps

Powerine Oil Company ISD Closure

Sep 1992 F:alky-cl\$

Table 1

CLOSURE COST ESTIMATE for the ALKY NEUTRALIZATION UNIT

<u>Task</u>	Sub <u>Task</u>		Sub Task <u>Total</u>	Task <u>Total</u>
1	Pl	REP, SUBMIT, & FINALIZE CLOSURE PLAN Performed by Powerine	\$0	\$0
2	No	OTIFICATION TO BEGIN CLOSURE	\$0	\$0
3	P	UBLIC NOTIFICATION	\$400	\$400
4	A B C D E	OIL SAMPLING and ANALYSIS Prep SAP and H&S Plan Drill and log 2 boreholes Analyze soil samples (6) Prepare soil assessment report Subtotal	\$2,000 \$1,430 \$1,200 \$3,000 \$7,630	\$7, 630
5	A B C	ACKFILL SUBSURFACE CONCRETE TANKS Clean fill Equipment and Labors Subtotal	\$1,778 \$1,384 \$3,162	\$3,162
7	A B C D	IPE FLUSH and DECON Flush sludge and neutralize Decon pipes Dispose pipes -non haz scrap metal Subtotal	\$200 \$200 \$100 \$500	\$500
8	C	LOSURE CERTIFICATION REPORT	\$3,000	\$3,000
9	C	LOSURE TOTAL		\$14,692

Notes:

Estimate based on assumption that no soil contaimination or remediation if required as a result of hazardous waste release

POWERINE Oil Company Santa Fe Springs, Ca Waste Analysis Plan August 1991 Rev:D F: alky-WAP

WASTE ANALYSIS PLAN for the ALKY NEUTRALIZATION UNIT

1.0 INTRODUCTION

Powerine Oil Company (POC) has prepared a Waste Analysis Plan as required by conditions specified in the Interim Status Document (ISD) for the Alky Neutralization Unit (ANU), granted on April 4,1981. The Waste Analysis Plan (WAP) has been prepared to satisfy the provisions of Section 67102(b) of the California Code of Regulations.

The WAP is segregated into two major sections, influent and effluent, sections 2 and 3 respectively. The principal influent to the ANU is alkylation regeneration bottoms which typically have a pH of less than 2. There are several other smaller influents streams, of a similar composition, which are basically periodic washes and flushes associated with the HF alkylation unit. Prior to neutralization, alky regeneration bottoms are classified as a RCRA hazardous waste, waste code D002 due to corrosivity.

After neutralization in the ANU the effluent is referred to as a neutralized regeneration bottoms. Normally treatment of the regeneration bottoms in the ANU renders the waste non-hazardous by Federal and State criteria.

1.1 APPLICABILITY OF RELATED REGULATIONS

The principal treatment process which occurs in the ANU is neutralization in tanks. Consequently most of the additional waste analysis specified in Section 67102(b)(6), are not required. Even Section 67258, which applies to treatment in tanks has only limited applicability because the waste stream is from a single source and because it is a relatively constant mixture of organics (polymer), water and hydrofluoric (HF) acid. Nonetheless if the neutralizing agent is changed from hydrated lime to caustic or potassium hydroxide, bench tests studies will be conducted to ensure that the integrity of the tank will not be diminished as a consequence.

2.0 INFLUENT SAMPLING AND ANALYSIS

No sampling of the influent waste stream is conducted on a routine basis. Safety considerations associated with collection of the acidic and highly corrosive regeneration bottoms outweigh the

value of information that can be obtained from routine analysis of the influent.

The composition of the influent is monitored through analysis of the HF acid in the circulating system of the alkylation unit. The circulating HF acid is tested for water content on a daily basis. As long as the water content of HF acid is less than 1.5 percent the composition of the regeneration bottoms are expected to remain fairly consistent. Above this limit the composition of the regeneration will not be a consideration because the alkylation unit will approach shut down. Non-routine sampling while subject to change is described more completely in the section below.

2.1 NON-ROUTINE INFLUENT SAMPLING AND ANALYSIS

2.1.1 Sampling Frequency

Non-routine influent sampling shall be conducted:

- 1. A minimum of once every five years
- Whenever the neutralization agent has changed
- Whenever the generating process has been altered such that the characterization of the influent may be altered.
- 4. Whenever hazardous waste regulation change such that the waste could be characterized as hazardous for some reason other than low pH (corrosivity).

2.1.2 Sample Location

The sample shall be taken from the sample valve on the line between the regeneration column and the polymer surge drum (PSD).

2.1.3 Number of Samples

Two samples will be required to fully characterize the influent because the regeneration bottoms are comprised of two distinct phases. The upper phase (lower specific gravity) is a polymer (hydrocarbon tar) and the lower phase (higher specific gravity) is a mixture of 60% hydrofluoric acid and 40% water which is referred to as constant boiling materials (CBMs).

2.1.4 Sample Collection, Preservation and Handling

Sample collection, preservation and handling shall be conducted in accordance with the methods prescribed in "Test Methods for Evaluating Solid Wastes, Physical & Chemical Methods" SW-846. Special precautions should be taken when taking the influent samples because of the corrosivity and potential threat to human health.

Samples of each phase should be allowed to settle. Testing should be conducted on the samples taken from the top of the polymer sample and from the bottom of the CBM sample.

2.1.5 Parameters and Methodologies

The parameters and test methodologies for non-routine influent analysis are specified in Table 2-1. Test shall be conducted by an outside lab.

Table 2 - 1
Non-routine Analysis of Influent Sample

2		Extract <u>Procedure</u>	Test <u>Preparation</u>	Test <u>Method</u>	
A.	Total Toxic Inorganics TTLC				
1	<u>Inorganics TTLC</u> Fluoride <u>Salts</u>	n a	3050 (3)	240-1 (h	`
	ridoride actis.	na	3050 (a)	340.1 (b	•
<u>B.</u>	Soluble Inorganics STLC			~ 11'	-
	Fluoride Series (MA)	WET (c)	3050 (a)	340.1 (b	1
_	I I THE TAKE A MAN HAMMAN	(with DI)	3030 (a)	340.1	1 110
		(WICH DI)			500
<u>C</u>	TCLP VOLATILE ORGANICS				
	Benzene	TCLP (d)	5030 (a)	8240 (a)
	Carbon Tetrachloride	TCLP (d)	5030 (a)	8240 (a	-
	Chlorobenzene	TCLP (d)	5030 (a)	8240 (a	•
	Chloroform	TCLP (d)	5030 (a)	8240 (a	•
	1,2-Dichloroethane	TCLP (d)	5030 (a)	8240 (a	•
	1,1-Dichloroethyene	TCLP (d)	5030 (a)	8240 (a	•
	Methyl Ethyl Ketone	TCLP (d)	5030 (a)	8240 (a	•
	Tetrachloroethylene	TCLP (d)	5030 (a)	8240 (a	•
	Trichloroethylene	TCLP (d)	5030 (a)	8240 (a	
	Vinyl Chloride	TCLP (d)	5030 (a)	8240 (a	•
			,	•	•
D.	TCLP SEMI-VOLATILE ORGANIC	S			
ı	o-Cresol	TCLP (d)	3550 (a)	8270 (a)
2	m-Cresol	TCLP (d)	3550 (a)	8270 (a	•
3	p-Cresol	TCLP (d)	3550 (a)	8270 (a	· ·
4	Cresols (total)	TCLP (d)	3550 (a)	8270 (a	*
5	1,4-Dichlorobenzene	TCLP (d)	3550 (a)	8270 (a	-
6	2,4-Dinitrotoluene	TCLP (d)	3550 (a)	8270 (a	•
7	Hexachlorobenzene	TCLP (d)	3550 (a)	8270 (a	•
8	Hexachloro-1,3-Butadiene	• •	3550 (a)	8270 (a	•
9	Hexachloroethane	TCLP (d)	3550 (a)	8270 (a	•
10	Nitrobenzene	TCLP (d)	3550 (a)	8270 (a	·
11	Pentachlorophenol	TCLP (d)	3550 (a)	8270 (a	:
12	Pyridine	TCLP (d)	3550 (a)	8270 (a	· .
13	2,4,5-Trichlorophenol	TCLP (d)	3550 (a)	8270 (a	•
14	2,4,6-Trichlorophenol	TCLP (d)	3550 (a)	8270 (a	•
	2,1,1	,	` '	-	•
<u>E.</u>	Corrosivity, Ignitability,	Reactivity			
	рН	na	na	9040 (a)
	Flash Point	na	na	1010 (a	
				•	
<u>F.</u>	Other Organic Tests				
1	Total Oil and Grease	na	3550 (a)	413.1 (b)
			• •	`	-
<u>G.</u>	Physical Parameters				
1	Specific Gravity	na	na	D-1298 (f)
2	Total Suspended Solids	na	na	\ 209.c (b)
	-			<u> </u>	 (
				1	-

Table 2 - 1

Non-routine Analysis of Influent Sample

Notes:

- (a) Test Methods for Evaluating Solid Wastes, Physical & Chemical Methods "SW-846, third edition, U.S. EPA
- (b) "Methods for Chemical Analysis of Water and Wastes", EPA-600/4-84-017, U.S. Environmental Protection Agency 1984.
- (c) Waste Extraction Procedure (WET) California Code of Regulations Section 66700, CAL- EPA
- (d) Toxicity Characteristic Leaching Procedure (TCLP) also EPA Method 1311 "Federal Register March 29,1990 Revision to Part 261 Appendix II
- (e) Conduct test only if total flouride content divided by 10 is greater than 180 mg/l, the STLC.
- (f) ASTM

2.1.6 Rationale for Selection of Parameters

The rationale for testing of the parameters listed in Table 2-1 is as follows:

Free HF The free hydrofluoric content is critical to determining the efficiency of the regenerator which has a direct impact on the operation of the ANU. The free HF in the polymer should be less than 1%. Higher concentrations indicate that the regeneration temperature is not being operated high enough or iso-butane stripping is not effective. There should be about an equal amount of HF and water in the CBM sample.

Fluorides Fluorides are measured to determine what percentage of fluorides will solubilize to form CaF.

Volatiles Volatiles are expected to rise overhead in the regeneration column. However there is a small possibility that some VOCs may have been trapped in larger complex organic compounds, polymers.

Semi-vols The chlorinated species of the semi-volatiles on the TCLP list of toxic substances are not expected to be found in the effluent. However there is a possibility that cresols and pyridine can be formed during the alkylation process.

pH The pH is measured to determine the acidity of the regeneration bottoms.

Flash The regeneration bottoms are not expected to flash at a temperature of less than 100 degrees F. This is a precautionary test.

TOG The Total Oil and Grease content of the regeneration bottoms is used to determine the organic fractions in the CBM and polymer.

The specific gravity is helpful in determining the composition of the waste in terms of solids, oil and water content.

TSS POC is charged by the recycling facility based on the solids content of the waste. This value is used to check against the recycling facility.

2.1.7 Recordkeeping

A copy of the non-routine analytical results shall be kept on file with the environmental group until the ANU is closed.

3.0 EFFLUENT SAMPLING AND ANALYSIS

Effluent sampling and analysis is segregated into two distinct phases:

- 1. Routine
- Non-routine

Each of these is described in greater detail in sections 3..1 and 3.2.

3.1 ROUTINE EFFLUENT SAMPLING AND ANALYSIS

Routine effluent sampling and analysis is conducted to ensure that the ANU is operating safely and efficiently on a day to day basis.

3.1.1 Sampling Frequency

Routine effluent sampling for pH shall be conducted a minimum of two times a day. Other parameters are analyzed once a week. (See section 3.1.5.)

3.1.2 Sampling Location

Effluent samples shall be taken from the alky neutralization tank.

3.1.3 Number of Samples

A single sample shall be deemed sufficient for analysis because the waste stream is from a single source and composition of the waste is fairly consistent. The neutralization tank is large comparison to the rate waste influent and tank mixers further homogenize the regeneration bottoms.

3.1.4 Sample Collection, Preservation and Handling

Sample collection, preservation and handling shall be conducted in accordance with the methods prescribed in "Test Methods for Evaluating Solid Wastes, Physical & Chemical Methods" SW-846.

Even with mixing, the polymer has a tendency to rise to the top of the neutralization tank. Consequently care should be taken to obtain a representative sample. The sample should taken from the point were the vacuum truck will draw, so that the characterization of the effluent is most representative the material that will eventually be taken offsite for recycling or disposal.

3.1.5 Parameters and Methodologies

The parameters, tests methodologies and sample frequency for routine effluent sampling are specified in Table 3-1.

Table 3 - 1

Routine Analysis of Effluent Sample

	Section 2	Frequency
<u>Parameter</u>	Method	Once per:
рн	pH paper	Shift
pH lab	9040	Week
Alkalinity	2320 B	Week
Solids Content (V%)	Centrifuge	Week
Total Oil & Grease	413.2	Week

Routine testing shall be conducted by POC internal lab.

3.1.6 Rationale for Selection of Parameters

The rationale for testing of the parameters listed in Table 3 - 1 is as follows:

pH The pH is measured by operating personnel to ensure that enough lime has been added.

pH lab The lab measures the pH to provide check on field analysis.

Alkalinity The alkalinity provides a measure of how much excess lime is present. Lime which fails to react is a waste of resources.

Analysis of solids provides indication of the amount of KF that has been formed. If the soils content is high, solids may be accumulated on the bottom of the tank. It is also used to check the fee basis for offsite recycling of the neutralized regeneration bottoms. The fees are partially based on solids content.

Total Oil Grease provides a gross measure of the organic content of the neutralized regeneration bottoms. This can be used to assess the viability of recycling the bottoms for hydrocarbon recovery and will provided a relative measure of the amount of polymer in relation to the total effluent.

3.1.7 Recordkeeping

During the calendar year, test results from routine effluent testing will be maintained at the lab. The data shall be recorded on the operations log for the alkylation unit or retained in some other fashion. These results will be submitted to the Environmental group no later than one month after the end of the calendar year. Routine analytical results will be maintained by the environmental group for a period of no less than 3 years.

3.2 NON-ROUTINE EFFLUENT SAMPLING AND ANALYSIS

3.2.1 Sampling Frequency

Non-routine influent sampling shall be conducted:

- 1. A minimum of once every five years
- 2. Whenever the neutralization agent has changed
- 3. Whenever the generating process has been altered such that the characterization of the influent may be altered.
- 4. Whenever hazardous waste regulation change such that the waste could be characterized as hazardous for some reason other than low pH (corrosivity).
- 5. Whenever results obtained during routine sampling and analysis varies from the from the previous analysis by more than 30%.

3.2.2 Sample Location

The sample shall be taken from the alky neutralization tank. As stated above the samples should be taken from a well mixed location.

3.2.3 Number of Samples

A single sample shall be deemed sufficient for characterization because the generating process is fairly consistent.

3.2.4 Sample Collection, Preservation and Handling

Sample collection, preservation and handling shall be conducted in accordance with the methods prescribed in "Test Methods for Evaluating Solid Wastes, Physical & Chemical Methods" SW-846.

3.2.5 Parameters and Methodologies

The parameters and test methodologies are specified in Table 3-2. Test shall be conducted by an outside lab.

Table 3 - 1
Non-routine Analysis of Effluent Sample

		Extract Procedure	Test <u>Prepara</u>	<u>ition</u>	Test <u>Method</u>	
Α.	Total Toxic					
	<u>Inorganics TTLC</u>					
1	Fluoride Salts	na	3050	(a)	340.1	(b)
<u>B.</u>	Soluble Inorganics STLC					
	Fluoride Salts (e)	WET (C)	3050	(a)	340.1	(b)
	entt -zie	(with DI)		` '		` '
		•				
<u>C</u> ,	TCLP VOLATILE ORGANICS	morn (4)	E020	(2)	0240	(5)
	Benzene	TCLP (d)	5030 5030		8240	(a)
	Carbon Tetrachloride Chlorobenzene	TCLP (d) TCLP (d)	5030	(a)	8240 8240	(a)
	Chloroform	TCLP (d) TCLP (d)	5030	(a) (a)	8240	(a) (a)
	1,2-Dichloroethane	TCLP (d)	5030	(a)	8240	(a)
	1,1-Dichloroethyene	TCLP (d)	5030	(a)	8240	(a)
	Methyl Ethyl Ketone	TCLP (d)	5030	(a)	8240	(a)
	Tetrachloroethylene	TCLP (d)		(a)	8240	(a)
	Trichloroethylene	TCLP (d)		(a)	8240	(a)
	Vinyl Chloride	TCLP (d)	5030		8240	(a)
_	TOTAL CONT. VOLUMETER ORGANIZA	22				
<u>D.</u>	TCLP SEMI-VOLATILE ORGANIC		2550	(-)	0070	(-)
1	o-Cresol	TCLP (d)	3550		8270	(a)
2	m-Cresol	TCLP (d)		(a)	8270	(a)
3	p-Cresol	TCLP (d)	3550	(a)	8270 8270	(a)
4 5	Cresols (total)	TCLP (d) TCLP (d)	3550 3550	(a) (a)	8270 8270	(a)
. 5 6	<pre>1,4-Dichlorobenzene 2,4-Dinitrotoluene</pre>	TCLP (d) TCLP (d)	3550		8270 8270	(a)
7	Hexachlorobenzene	TCLP (d)	3550	(a)	8270 8270	(a)
8	Hexachloro-1,3-Butadiene	• •	3550	(a) (a)	8270 8270	(a) (a)
9	Hexachloroethane	TCLP (d)	3550	(a)	8270	(a)
10	Nitrobenzene	TCLP (d)	3550	(a)	8270	(a)
11	Pentachlorophenol	TCLP (d)	3550	(a)	8270 8270	(a)
12	Pyridine	TCLP (d)	3550	(a)	8270	(a)
13	2,4,5-Trichlorophenol	TCLP (d)	3550	(a)	8270	(a)
14		TCLP (d)	3550		8270	(a)
	2,4,0 irromforophenor	10111 (4)	3330	(ω)	0270	(4)
	Corrosivity, Ignitability	<u>, Reactivity</u>				
	рн	na	na		9040	(a)
2	Flash Point	na	na		1010	(a)
<u>F.</u>	Other Organic Tests					
	Total Oil and Grease	na	3550	(a)	413.1	(b)
G.	Physical Parameters					
	Specific Gravity	na	na		D-1298	(f)
	Total Suspended Solids	na	na na		209.c	(b)
2	TO CAT DADPONACA DOTTAD	114	110		203.0	(~)

Table 3 - 1

Non-routine Analysis of Effluent Sample

Notes:

- (a) Test Methods for Evaluating Solid Wastes, Physical & Chemical Methods "SW-846, third edition, U.S. EPA
- (b) "Methods for Chemical Analysis of Water and Wastes", EPA-600/4-84-017, U.S. Environmental Protection Agency 1984.
- (c) Waste Extraction Procedure (WET) California Code of Regulations Section 66700, CAL- EPA
- (d) Toxicity Characteristic Leaching Procedure (TCLP) also EPA Method 1311 "Federal Register March 29,1990 Revision to Part 261 Appendix II
- (e) Conduct test only if total flouride content divided by 10 is greater than 180 mg/l, the STLC.
- (f) ASTM

3.2.6 Rationale for Selection of Parameters

The rationale for testing of the parameters listed in Table 3-2 is as follows:

Fluorides Fluorides are measured to determine what percentage of suspended solids are fluoride salts specifically CaF.

Volatiles While volatiles organic compounds (VOCs) are expected to rise overhead in the regeneration column there is a small possibility that VOCs may have been trapped in larger complex organic compounds, polymers.

Semi-vols Chlorinated species of the semi-volatiles on the TCLP list of toxic substances are not expected to be found in the effluent. However there is a possibility that cresols and pyridine was formed in the during the alkylation process.

pH The pH is measured to ensure that enough lime has been added.

Flash The regeneration bottoms are not expected to flash at a temperature of less than 100 degrees F. This is a precautionary test.

TOG The organic content of the neutralized regeneration bottoms is of interest because recycling facilities are recovering the polymer. The Total Oil and Grease (TOG) content provides a gross measure of the organic content.

The specific gravity is helpful in determining the composition of the waste in terms of solids, oil and water content.

TSS POC is charged by the recycling facility based on the solids content of the waste. This value is used to check against the recycling facility.

3.2.7 Recordkeeping

A copy of the analytical results shall be kept on file with the environmental group until the ANU is closed.

12-*20-8*

April 15, 1991 a Mind

DEPARTMENT OF HEALTH SERVICES

TOXIC SUBSTANCES CONTROL PROGRAM (REGION 3) 1405 N. SAN FERNANDO BOULEVARD, SUITE 300 BURBANK, CA 91504 (818) 567-3000

> Ms. June M. Christian Powerline Oil Company 12354 Lakeland P.O. Box 2108 Santa Fe Springs, CA 90620

Dear Ms. Christian:

REVISED PART A APPLICATION FOR TOXICITY CHARACTERISTIC WASTE, FACILITY EPA ID# CADO08383291

This letter will confirm your telephone conversation with Andy Bajwa of this office on April 1, 1991.

We received your Part A Permit Application on March 17, 1991, regarding the notification requirement of newly identified Toxicity Characteristic (TC) waste. We did a detailed review of your Part A permit application. During the telephone conversation on April 1, you told Mr. Bajwa that your submittal on March 17 was in error and no TC wastes are handled by your facility. This Department has come to the conclusion that your facility is not affected by the TC Regulations and does not require any modification of your existing Interim Status Document (ISD).

If you have any questions concerning your application, you may contact Andy Bajwa of my staff at (818) 567-3122.

Sincerely,

Scott Simpson, Chief

Facility Management Branch

cc: James Breitlow
U.S. EPA, Region IX
75 Hawthorne Street
San Francisco, CA 94105

Paul Blais Hazardous Waste Management Branch Toxic Substances Control Program 714/744 P Street P.O. Box 942732 Sacramento, CA 94234-7320